



# Draping Glass with KL-Board Mold Blocks - a Petra Kaiser © Project

For more ideas visit us at [www.kaiserlee.com](http://www.kaiserlee.com) and sign up for our Newsletter!



### Tip:

All your triangles have to have the same heights - to ensure a leveled bowl. Use a sanding block from the KLB tool kit to level them.



Prepare for cutting 6 triangles from 12" x 4" x 1.5" or 2" thick Kaiser Lee Board



### Firing

300° F up to 1000° F hold for 10 min.  
Fast to 1220° F hold for 5 min  
Fast to 960° F hold for 60 min  
300° F down to 500°  
Turn off and let cool to room temperature



Set the triangles on the Kaiser Lee Board kiln shelf and cover the top with used fiber paper strips. Then dust the set up with dry kiln wash powder.



Pre-fuse a glass piece first. It can be round, square, uneven - it will always turn out right.  
For the drape firing place the décor side down .

