

Free Flowing Pendant - The Hidden Bail Part 2

How To:

Possible Pendant Shapes



With this mold you will be able to produce concave pendants which will look like they are free flowing on your chain. This will give your creations a distinguished design element.

Step 1: Cut a piece of iridescent glass a bit smaller than your carved slot and place it irid side down into the slot. Place your rolled up fiber paper into its slot.






Step 2: Place a piece of iridescent glass, irid side down onto the board and draw an outline shape - design onto the glass. Cut your glass and start decorating it. Fire your piece.

Tip:

Bails need to be in the upper third of your pendant to avoid rotation of the finished glass piece.



Finishing Step: Take two pieces of the crinkle wire and cramp it into one end of the magnetic scrimp bails. String about 5 to 7 beads before you go through the pendant. String the same amount of beads and cut the wires to the desired length with a pair of wire cutters before you screw on the other side of the magnetic clasp.



Box Content

Box 1: Fusing Supplies

- 1 KL Board Mold 3.5" x 3"
- 6 Fiber Rolls
- 6 pieces of iridescent clear glass COE 90 or 96 3" x 2"
- 1 Zuper Glue **\$25**
- Additional Inspirational Ideas

Box 2: Beading Supplies

- Small beads **\$26**
- 12 crinkled wires
- 6 scrimp magnet clasps
- Small screw driver for magnet clasps

Or get both boxes for only \$49



Fuse It
with
Kaiser Lee Board



- www.kaiserlee.com
- petra@kaiserlee.com
- Phone (239)540.1137

Enjoy this original Petra Kaiser Project ! ©

P
R
O
J
E
C
T
I
N
A
B
O
X